


# SERVICE CYLINDER HEADS

Remanufactured 6.0L Cylinder Heads  
Identification and Replacement



*Please Note: VIN # is not sufficient for identifying proper replacement.*


THREE 8MM BOLT HOLES



INJECTOR HOLES CHECKED FOR CRACKS AND BURRS

**GA30000R**  
(18mm Dowel)


TWO 10MM BOLT HOLES



INJECTOR HOLES CHECKED FOR CRACKS AND BURRS

**GA31000R**  
(20mm Dowel)


TWO 8MM BOLT HOLES



INJECTOR HOLES CHECKED FOR CRACKS AND BURRS

**GA32000R**  
(20mm Dowel)


EIGHT 8MM BOLT HOLES  
FOUR FREEZE PLUGS




INJECTOR HOLES CHECKED FOR CRACKS AND BURRS

**GA33000R**  
(18mm Dowel)

EIGHT 8MM BOLT HOLES



INJECTOR HOLES CHECKED FOR CRACKS AND BURRS



FIND MORE PRODUCTS:  
[WWW.GRIZZLYTOUGH.COM](http://WWW.GRIZZLYTOUGH.COM)